

Inspection Report

Customer: Wise Components

Part Number, Quantity, Date Code: 29F52SCX, 9000 PCS, D/C 0048 5k,
0042 4k,

Manufacturer: Fairchild Semi

Inspection Sample:

1-Source inspected 200 components as per AQL. All 200 were inspected visually and pictures taken of (8)factory sealed boxes and (1) opened box for inspection .

Source: AVL approved supplier (Tier 1), 0% RMA's for FYA'07.

Conclusion:

The components were genuine, new and original.

The component passed the acetone test.

The leads show no-use and factory original packaging.

The components showed no obvious evidence of prior use such cracks, imperfections or anomalies.

Components were delivered in original packaging with dessicant and MSL protection.

1-Source suggests to proceed with processing order to customer.



